





















M905C





- A 4x70, T20 x 112
- B 5x100, T25 x 13
- C 4x50, T20 x 88
- D 3,5x30, T15 x 300
- E 4x40, T20 x 144
- F 4x60, T20 x 64
- G 3x12 x 6
- H 2,5x50 x 216
- J 4x30 x 5
- K 3,1x15 x 5 pack
- L 10x60 x 72




№		PCS			
			mm	mm	mm
1		10		1180	1900
2		1		60	1660
3		1		380	1900
4		1		380	1900
5		2		772	1801
6		1		772	1801
7		1		238	1193
8		1		124	1170
9		1		238	1193
10		2		124	1170
11		4		240	1180
12		11	60	60	1810
13		1	30	57	1600
14		2		1172	1910
15		2		1172	1910
16		2	60	60	1880
17		1	60	60	1064
18		2	10	284	673
19		3	10	284	1180
20		2	10	89	673
21		3	10	89	1180
22		2	10	189	1579
23		2	10	189	1180
24		10	10	154	1180
25		4	10	154	872
26		2	10	154	399
27		1	60	82	1839
28		2	60	82	1839
29		1	60	82	1688
30		9	40	120	1590
31		9	40	120	1169
32		12	40	120	252
33		4	12	1180	1900

34		4	12	859	1180
35		2	12	272	1579
36		2	12	272	1180
37		8	13	92	1890
38		5	13	92	1885
39		2	13	92	1909
40		1		1040	1900
41		1		231	1110
42		2		1064	1172
43		1		60	839
44		1		170	1900
45		1		170	1900
46		1	30	57	839
47		1	60	82	1839
48		1	60	82	925
49		12			1660
50		5 pack			
51		6			1000
52		1	T25		
53		1	T20		
54		1	T15		
55		2			
56		2			
57		8			
58		18			
59		18			
60		9			
61		9			
62		2			
63		2			
64		1			
65		1			


1




2



3



4



F x4

F x4

C x16

60


8

A x24


1

62


8




5






6



7




F_{x4}




8


$x=y$




A




B




Det A




Det B




Det C




C





D




Det D



9



C x4





8

7


56

7





G x6


10




11



C x2



F x8




12

L x72

58






30

31




13

$a=b$



4886



14

A x24

32

32

2759

339

540

560


40


540

540


1180 !

2360 !





16




17


18

H x26


19



Ø2,5



19




18

20


H x26




21






21

Ø2,5








25





24

H x30


24



21





22






23

$a=b$



$a=b$



25

14-19mm

60

65

61


14-19mm


65

5

6

5





27

Int.

55

D x4

Int.

Ø12

Int.

D x4

55

Int.

Ø12

